




Sample IR building survey for HVAC and Moisture



Description: Lobby under skylight may have leak outside air temp is in the low 100's



Sample IR building survey for HVAC and Moisture




Description: Room 244 leak may be from above floor tub drain

Sample IR building survey for HVAC and Moisture




Sample IR building survey for HVAC and Moisture




Description: Meeting room warm due too infiltration

Sample IR building survey for HVAC and Moisture



Sample IR building survey for HVAC and Moisture




Description: Infiltration meeting rooms

Sample IR building survey for HVAC and Moisture



Description: missing insulation

Sample IR building survey for HVAC and Moisture




Description: Kitchen supply drawn into hood exhaust energy waste

Sample IR building survey for HVAC and Moisture




Sample IR building survey for HVAC and Moisture




Description: Kitchen supply very close to return

Sample IR building survey for HVAC and Moisture




Sample IR building survey for HVAC and Moisture



Description: Snack area not ventilated and Leslie's office is behind the wall




Sample IR building survey for HVAC and Moisture



Description: Leslie's office large heat infiltration and lack of air flow due too leaking ductwork causes warm office




Sample IR building survey for HVAC and Moisture




Description: Rtu 3rd floor east-cond fan air short cycling

Sample IR building survey for HVAC and Moisture



Sample IR building survey for HVAC and Moisture




Description: roof view looking to the front

Sample IR building survey for HVAC and Moisture




Sample IR building survey for HVAC and Moisture




RTU 2 main lobby bad compressor- blown Schrader port- repaired and tried to charge unit but valves in compressor are damaged



Sample IR building survey for HVAC and Moisture



Sample IR building survey for HVAC and Moisture




Description: Split system for computer room plugged condenser coil and is tripping


Sample IR building survey for HVAC and Moisture




Sample IR building survey for HVAC and Moisture



Sample IR building survey for HVAC and Moisture




Sample IR building survey for HVAC and Moisture



Description: energy loss in blue cold air leaking out instead of blowing into the space.




Sample IR building survey for HVAC and Moisture



Description: Dirty coil blocked air flow in red will over work the compressors
Blue is air leakage




Sample IR building survey for HVAC and Moisture



Boiler with major problem



Sample IR building survey for HVAC and Moisture



Sample IR building survey for HVAC and Moisture

